

## Findings Photos

**Project Name:** Schmeikel Boy Sausages  
**Project Number:** 12345 - 2



**Damage Type:** Suspect Visible Mold  
**Affected Area Size:** 90 Sq Ft  
**Direction:** SE  
**FindingDate:** 1/1/2007

**Zone:** Pig Storage  
**Area Name:** Pig Humping Area  
**Area Type:** Bedroom  
**Finding ID:** 29059367-93E7-4ECA-BC48-B42A51CB0BAE

**Notes:** Enitre SE wall is distressed

**Recommendations:**

Remove or clean all materials with suspect visible mold.



**Damage Type:** Water Damage  
**Affected Area Size:** 100 Sq Ft  
**Direction:** NW  
**FindingDate:** 2/25/2007

**Zone:** Pork Rendering  
**Area Name:** Living Room  
**Area Type:** Living Room  
**Finding ID:** BD32AEE1-98D4-44F0-B439-0590209EB892

**Notes:**

**Recommendations:**

Remove all damaged dry wall at least 2 feet past the damaged area. Clean all wood or metal studs

<b>Project Name:</b> Schmeikel Boy Sausages	<b>Inspection Date:</b> 1/1/2007	<b>Event ID:</b> D47AE19D-FB20-43CB-8ACA-434E97DC5AE2
<b>Project Number:</b> 12345 - 2		<b>City:</b> Chicago
<b>Site Address:</b> 425 E McFetridge Dr		<b>State:</b> IL
<b>Lot Number:</b> 666	<b>Parcel:</b> Undeveloped # 3	<b>Zip:</b> 60605
		<b>Lat:</b> 41.8649893423434
		<b>Lon:</b> -87.6183550653931

Friday, June 01, 2007

Indoor Environment Evaluation

Finding Photos - Page 1 of 1