

Project and Site Data

Project Number: 12345 - 2

| | | | |
|-------------------------|-----------------------------|------------------------------|--|
| Project Name: | Schmeikel Boy Sausages | Client: | Jose Shmendrik |
| Subdivision: | The Loop | Client Address: | 99 Tube Steak Drive Chicago, IL 45872 |
| Site Address: | 425 E McFetridge Dr | Client Phone: | 565.125.9874 |
| 2nd Address: | North Side of Soldier Field | Client Email: | BigWeenie@HotDog.Net |
| State: | IL | Lat: | 41.8649893423434 |
| City: | Chicago | Lon: | -87.6183550653931 |
| Zip: | 60605 | Building Orientation: | East |
| Site Phone: | 555.555.5554 | Building Type: | Commercial |
| Site Email: | Casing@Filler.com | Scientist Name: | Esteban J. Vekavonavich |
| Lot Number: | 666 | Accompanying Persons: | Henrie Shmendrik, Head Meat |
| Parcel: | Undeveloped # 3 | | |
| Inspection Date: | 1/1/2007 | Inspection Type: | Water Intrusion |
| Inspection Time: | 9:17 AM | Inspection Reason: | Lake Michigan Overflow |

Pass the brautwurst.

| | | | |
|--|----------------------------|--|------------|
| Adults Residing: | 12 | <input type="checkbox"/> Vacated | |
| Children Residing: | 0 | <input checked="" type="checkbox"/> Previous Testing | |
| <input checked="" type="checkbox"/> Adverse Health Conditions | | <input checked="" type="checkbox"/> Report Copy | |
| Symptom Duration: | 1month | Construction Date: | 2/8/1950 |
| Symptom Type: | Asthma Frequency Increased | Space Build-Out Date: | 1/10/2002 |
| <input checked="" type="checkbox"/> Water Intrusion Events | Water Leak-General | Renovation Date: | 4/5/2000 |
| <input checked="" type="checkbox"/> Solution Attempts | Client Repainted | Date Noticed: | 12/31/2006 |

Smells like dead pig

| | | | |
|--|------------------|---|---------|
| A/C System Type: | Roof Top Package | Heat System Type: | Central |
| <input checked="" type="checkbox"/> A/C Operational | | <input checked="" type="checkbox"/> Heat Operational | |
| <input checked="" type="checkbox"/> A/C Changes Made | | <input checked="" type="checkbox"/> Heat Changes Made | |

Dripping, drip pan full
Rusted

| | | |
|-----------------------------------|-------|--|
| Weather Conditions: | Windy | <input checked="" type="checkbox"/> Slopes |
| Outside Temperature: | 74 | Slope Note: Minor |
| Outside Relative Humidity: | 55 | <input checked="" type="checkbox"/> Water Source |
| Room Count: | 7 | Water Type: Well/Septic |
| Floor Count: | 2 | |

| | | | |
|---------------------------|---------|--------------------------|----------|
| Construction Type: | | Siding Condition: | Poor |
| Framing | CBS | Roof: | Built-up |
| Framing Condition: | Poor | Roof Condition: | Poor |
| Siding | Unknown | | |

Attached Exterior Structures
Storage

Unattached Exterior Structures
Slaughterhouse
Slum

| | | | | | | | |
|------------------------|------------------------|-------------------------|--------------------------------------|---------------|------------------|-------------|-------------------|
| Project Name: | Schmeikel Boy Sausages | Event ID: | D47AE19D-FB20-43CB-8ACA-434E97DC5AE2 | | | | |
| Project Number: | 12345 - 2 | Inspection Date: | 1/1/2007 | | | | |
| Site Address: | 425 E McFetridge Dr | City: | Chicago | State: | IL | Zip: | 60605 |
| Lot Number: | 666 | Parcel: | Undeveloped # 3 | Lat: | 41.8649893423434 | Lon: | -87.6183550653931 |